



If the control shows that de mesh has at least the minimum absorption capacity required, it can continues working another period of 12 months. Then, the controller agent will give you a **certificated as an evidence of the results**. If the net does not pass the audit, it must be removed.





When should safety net be inspected?
Apart from annualy tests, the user should do a visual revision before starting the works. Moreover, a competent person should carry up a control of the safety nets status, every 7 days after a handover. Finally, the safety manager should overhaul the netting after living and adverse weather .